03560.003354

<u>PATENT</u>

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

Takahiro MATSUMOTO et al.

Application No.: 10/662,408

Filed: September 16, 2003

For: POSITION DETECTING DEVICE AND POSITION DETECTING METHOD

U.S. Patent No. 6,999,893 B2

DEXAMINE: T. S. Lau

Group Art Unit: 2863

June 1, 2006

June 1, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Issued: February 14, 2006

Attention: Certificate of Correction Branch

Of Correction

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and

Trademark Office due to errors which appear in the printed patent as a result of U.S. Patent and

Trademark Office mistakes and mistakes of a minor nature which are not the fault of the U.S.

Patent and Trademark Office.

06/02/2006 SZEWDIE1 00000018 6999893 01 FC:1811 100.09 OP Accompanying this letter is a check for \$100.00 to cover the statutory fee for such

Certificate of Correction. Any additional fee required by this paper may be charged to Deposit

Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentees

Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
SEW/eab

DC_MAIN 242274v1

PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,999,893 B2

DATED : February 14, 2006

INVENTOR(S): Takahiro MATSUMOTO et al.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE:

In item "(*) Notice:," line 3, "39 days" should read -- 0 days --.

In item "(56) References Cited," under "U.S. PATENT DOCUMENTS," in the second column, the seventh-listed patent "6,844,918 B1 1/2005 Navarro Y Koren et al. . 355/53" should read -- 6,844,918 B2 1/2005 Navarro Y Koren et al. . 355/53 ---

In item "(57) ABSTRACT," line 12, "apparatuses" should read -- apparatus --.

IN THE DRAWINGS:

In "Sheet 20 of 21," in "FIG. 23," in the legend underneath the drawing, "RESIST" should read -- RESISTS --.

COLUMN 1:

Line 23, "later," should read -- latter, --.

Line 55, "rectile" should read -- reticle --.

Line 56, "rectile." should read -- reticle. --.


MAILING ADDRESS OF SENDER:

PATENT NO. 6,999,893 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page





Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,999,893 B2

DATED : February 14, 2006

INVENTOR(S): Takahiro MATSUMOTO et al.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 58, "apparatuses" should read -- apparatus --.

COLUMN 4:

Line 37, "processes," should read -- process, --. Line 61, "in to" should read -- into --.

COLUMN 6:

Line 37, "sents" should read -- sent --.

COLUMN 7:


Line 56, "descried." should read -- described. --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,999,893 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page



PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,999,893 B2

DATED : February 14, 2006

INVENTOR(S): Takahiro MATSUMOTO et al.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8:

Line 31, "coefficient a" should read -- coefficient α --.

Line 39, "qx, qy," should read -- θx , θy , --.

Line 56, "component ei" should read -- component ei --.

Line 57, 'component ei" should read -- component ei -- and "ei=Ri+Ki" should read -- εi=Ri+Ki --.

Line 58, "component ei," should read -- component εi, --.

Line 63, "and ei" should read -- and Ei --.

COLUMN 9:

Line 2, "coefficient a" should read -- coefficient α --.

Line 32, "way" should read -- may --.

COLUMN 10:

Line 52, "off set" should read -- offset --.

Line 56, "(MA)=0.4." should read -- (NA)=0.4, --.


Line 63, "riot" should read -- right --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

PATENT NO. 6,999,893 B2

No. of add'l. copies @ 30¢ per page





PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,999,893 B2

DATED : February 14, 2006

INVENTOR(S): Takahiro MATSUMOTO et al.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11:

Line 5, "illustrate" should read -- illustrates --.

Line 17, "in to" should read -- into --.

Line 52, "position" should read -- positions --.

COLUMN 12:

Line 17, "in to" should read -- into --.

Line 27, "NA 0.6" should read -- NA=0.6 --.

Line 28, "NA 0.4" should read -- NA=0.4 --.

Line 42, "resulted" should read -- results --.

COLUMN 13:

Line 21, "in to" should read -- into --.

COLUMN 14:

Line 30, "in to" should read -- into --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,999,893 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page

JUN 62006

